



Austin Healey Mark I BJ 8 12v

Effective October 2019  
Prices Subject To Change  
Without Notice!

VALVE LIFT	DURATION	DURATION @ .050	GRIND NUMBER	DESCRIPTION	REGRIND	HARDWELD	BILLET
.415/.415	290°/290°	252°/252°	1	Strong top end for competition engines.	40-020 \$290.00	N/A	N/A
.400/.400	260°/260°	232°/232°	7	Improved mid and upper end performance. Use in modified engines.	40-010 \$290.00	N/A	N/A
.380/.380	248°/248°	214°/214°	84	Good all around cam with broad power range for stock engines.	40-000 \$290.00	N/A	N/A
.335/.335	223°/223°	190°/190°	1104	Web Camshaft will restore your stock cam back to the original specifications. If the lobes are severely worn they can be hard welded, additional charges will apply.	40-050 \$290.00	N/A	N/A
Lifters Regind OEM				We will precision grind your stock lifters to factory specifications. Use with all reground cams. Price Per Set (12).			RL-043 \$94.00

Severe lobe damage can be repaired by welding. Please call for more details.